

STARTIN USED VEHICLE PRE-SALES INSPECTION SCHEDULE

Stock No. 124065
 Purchaser _____

Make ISUZU
 Model P. MAY
 Reg no. WF72UGD
 Chassis _____
 Engine 1.9
 Mileage 26008

The following items have been checked

Date	<u>27/2/26</u>
Inspected by	<u>Wayne Thornley</u>

Column 1 O.K. Not Applicable Needs Attention
 Column 2 Corrected, repaired or replaced

	1	2		1	2
1. Engine oil level	✓		33. Indicator lights	✓	
2. Brake fluid level	✓		34. Headlight flasher	✓	
3. Check coolant	✓		35. Hazard Warning	✓	
4. Anti freeze	✓		36. Instrument panel lights	✓	
5. Gearbox/Axle levels	✓		37. Courtesy lights	✓	
6. Battery test	✓		38. W/screen wipers	✓	
7. Battery and earth connectors	✓		39. W/screen washers	✓	
8. Radiator hoses & clips	✓		40. Heater/ Heater blower	✓	
9. Fan belt/Other drive belts	✓		41. Rear screen heater	✓	
10. Under bonnet visual check	✓		42. Horn	✓	
11. Bonnet lock & Safety catch	✓		43. Fuel indicator	✓	
12. Aircon temp	✓		44. Clock	✓	
13. Wheel nuts / Locking nut check	✓		45. Stereo	✓	
14. Brake pads/linings	✓		46. USB interface	✓	
15. Brake hoses	✓		47. Door closing	✓	
16. Brake pipes & exterior hydraulics	✓		48. Window mechanism	✓	
17. Exhaust Sytem	✓		49. Child locks	✓	
18. Front wheel alignment	✓		50. Door lock inside/outside	✓	
19. Suspension	✓		51. Boot lock	✓	
20. Shock absorbers	✓		52. Driving mirror	✓	
21. Steering rods & linkage	✓		53. Seat security	✓	
22. Steering box	✓		54. Seat belts	✓	
23. Underbody inspection	✓		55. Wheel brace	✓	
24. Oil leaks	✓		56. Inflation kit	○	
25. Windscreen (chips)	✓		57. Lifting jack	✓	
26. Reverse camera operation	✓		58. Change number plates	✗	
27. Headlights dipped/main	✓		59. Parking sensors	✓	
28. Side lights	✓		60. Navigation system check	✓	
29. Reverse lights	✓		Fitted accessory Check	✓	
30. Stop light	✓		61		
31. Fog light	✓		62		
32. Number plate lights	✓		63		



Startin Tractors LTD. Ashby Road, Twycross, Atherstone, Warwickshire CV9 3PW

Rear Seat Trim missing

Nearside

Front



Depth 7
Pressure 36
Adjusted _____

Brake Lining
30 % Worn

Condition ok

Offside

Front



Depth 7
Pressure 36
Adjusted _____

Brake Lining
30 % Worn

Condition ok

Rear



Depth 7
Pressure _____
Adjusted _____

Brake Lining
30 % Worn

Condition ok

Rear



Depth 7
Pressure _____
Adjusted _____

Brake Lining
30 % Worn

Condition ok

Spare



Depth 9
Pressure 40
Adjusted _____

N.B. Tyres to be measured on the inside, middle and outside in mm.

Isuzu recall check. Yes N/A
Outstanding recalls completed. Yes

Last service done
MOT required Yes No

N.B. MOT required if less than 6 months remaining on vehicles over 3 years old.